


**ATTENZIONE - ATTENTION - ACHTUNG**

- Per lo smontaggio degli utensili utilizzare sempre la chiave di contrasto come indicato nel manuale d'uso.
- For disassembly of the tools use always the contrast key as mentioned in the user instructions.
- Fuer das Abmontieren der Werkzeuge immer den Gegenschlüssel benutzen wie in der Bedienungsanleitung erwaeht.


- Chiave inclusa
- Key included
- Schlüssel inbegriffen

| Cod. MT     | Mandrino Spindle Spindel | I   | RPM  | Coppia Max Max Torque Max Drehmoment | Reversibile lato mandrino/contromandrino Reversible sub/main spindle side Umkehrbare Spindelseite/ Gegenspindelseite | Lubrificazione est. Ext. coolant Ausseukuehlung | CHIAVI NON INCLUSE Keys not included Schlüssel nicht einbegriffen |        |              |
|-------------|--------------------------|-----|------|--------------------------------------|--|---|---|--------|--------------|
| DW 02980332 | ERA32                    | 1:1 | 6000 | 100Nm                                | X  | X   | CHUB30  | CHUB50 | CHTAER32ZC ▪ |

**HAAS**  
**MOD: ST40/45Y (BMT75)**  
**MODULO MOTORIZZATO RADIALE DISASSATO 50mm ORIENTABILE ±25°**  
 Radial ±25° adjustable angle driven tool re-directed by 50mm  
 Radial angetriebenes Werkzeug schwenkbar ±25° achsversetzt um 50mm



**M.T. srl**  
 Via Casino Albini 480  
 Tel. 0541/956034-957884  
 Fax 0541/956341  
 47842 S. GIOVANNI IN M. (RN)  
 e-mail: mtma@mtmarchetti.com  
 http://www.mtmarchetti.com



Subject to change without notice.